

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 7 4 9	DATE	F e b . 9 . 2 0 1 6
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>①Due to the improper material of the contact area of the switch for the rear wheel brake light, the contact area may wear during the use process. Therefore, if it is used continuously, wear may progress and the function of the said switch may worsen, and that may cause a lighting failure of the brake light.</p> <p>②Due to the improper material of the contact area of the side stand switch, the contact area may wear during the use process. Therefore, if it is used continuously, the wear may progress and the function of the said switch may worsen. As a result, the engine rotation speed may not go up and the vehicle may not start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B H - U A 0 7 J	GEAR BX50N	2 0 1 5	2, 7 9 4
	GEAR BX50		2, 0 4 2
		TOTAL	4, 8 3 6