

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3748	DATE	Feb. 9. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	The slide-glide door of the route bus model has a rotating shaft and a air cylinder bracket, improperly fixed with each other. The spring pin fastening the shaft and the bracket may be cracked and broken if the bus is kept in operation under such a condition. In the worst case, the spring pins on the both sides of the door will be broken, which may cause the door to open during driving, or the driver may become unable to operate the door from the driver's seat.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KL-HU2PMEA KL-HU2PMEE KL-HU2PMEEKAI	[HINO Blue Ribbon City]	2002~2005	89	
KL-HU2PPEE KL-HU2PPEEKAI		2003~2005	52	
ACG-HU8JLFP BJG-HU8JLFP		2005~2010	259	
LJG-HU8JLGP LNG-HU8JLGP LNG-HU8JLGPKAI		2010~2015	177	
ACG-HU8JMFP ACG-HU8JMFPKAI BJG-HU8JMFP		2005~2010	202	
LJG-HU8JMGP LNG-HU8JMGP		2010~2015	141	
FCBUS		[TOYOTA FCBUS]	2014	2
			TOTAL	922