

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |  |      |            |
|-----------------------|--|------|------------|
| CAMPAIGN No.          | 3739   | DATE | Feb.3.2016 |
| MANUFACTURER          | TOYOTA   |      |            |
| DESCRIPTION OF DEFECT | In the airbag control unit of the subject vehicles equipped with curtain shield airbags, due to improper start-up programming for the airbag system, there is a possibility that the zero-point for the rollover sensor may not be properly calibrated if the vehicle rides over a step at certain places such as uneven ground immediately after the engine start. In this condition, the rollover sensor may erroneously detect a rollover if the vehicle inclines, causing both of the curtain shield airbags and the seat belt pre-tensioners to be activated. |      |            |

| TYPE       | COMMERCIAL NAME      | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|----------------------|---------------------|-------------------|
| GH-UZJ100W | [LAND CRUISER WAGON] | 2002-2006           | 1,463             |
| KR-HDJ101K | [LAND CRUISER]       |                     | 216               |
|            |                      | TOTAL               | 1,679             |