

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3767	DATE	Feb 17,2016
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>Due to inadequate strength of the torque rod on wheel cranes shock absorbers, it is possible that the stress to the subject support installation unit may exceed it's rated fatigue limit when the brakes are suddenly applied. This may lead to cracking of the torque rod support installation unit and, with continuous use in this condition, to breakage of the torque support installation unit and the risk of the torque rod falling off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SD-T001	TADANO 「CREVO350」	2004-2008	152
		TOTAL	152