

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3773	DATE	Feb 26, 2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to inappropriate programming of the engine control unit in certain starters on the engine of the vehicles, the starter pinion gear may fit excessively with ring gear of the torque converter, if the operator shifts from P to N and push the ignition switch when engine starts. As the result, the pinion gear of the starter may be broken by the impact during fitting, and noise may occur when the engine starts. In the worst case, the engine is unable to be started.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GJ6	「IMPREZA」	2014~2015	199
DBA-GJ7		2014~2015	1,874
DBA-GP6		2014~2015	538
DBA-GP7		2014~2015	13,939
		TOTAL	16,550