

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2299	DATE	Feb.24, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION (Japanese Importer : ITOCHU Automobile Corporation)		
DESCRIPTION OF DEFECT	Due to improper heat treatment of the tappet and cylinder head assembly process of the engine, contamination between the tappet and camshaft may cause abnormal wear to tappet and cam, and noises may occur from the engine. In worse case, it may cause the engine to stall while riding.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CX112	GLADIUS	2013	60
C7111	V-Strom 650	2013	40
C5111	GSR750	2013	8
C5112		2013	10
TOTAL			118