

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	2316	DATE	March 23, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION (Japanese Importer : ITOCHU Automobile Corporation)		
DESCRIPTION OF DEFECT	<p>Due to improper moisture control at the production of Power module (Circuit board) in Regulate Rectifier, Power module is detached from Regulate Rectifier body with cooling fins and the temperature of regulating device in Power module is over its heat resistance temperature.</p> <p>If continued to use with this condition, this can cause discharge of the battery. In the worst case, it can lead to engine stalling during running and be impossible to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VT53A	V-Strom 1000	2008	30
B9112	GSR600	2008~2010	50
GX71A	B-KING	2008	430
GX71B		2008	30
GX72A	Hayabusa	2008~2010	4,157
CK111		2011~2012	1,300
GN7EA	GSX-R600	2008~2010	460

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GR7LA	GSX-R750	2008~2010	610
CX111	GLADIUS	2009~2011	190
CX112		2009~2011	179
CT111	BOULEVARD C109R	2008~2009	40
		TOTAL	7,476