## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3765	DATE	Mar 3, 2016	
MANUFACTURER	SUZUKI MO'	TOR CORPOR	ATION	
DESCRIPTION OF DEFECT	Due to improper filling up of oil into the compressor of the air conditioner, the compressor may experience insufficient lubrication inside it while using the air conditioner.  Therefore, with using the air conditioner as it is, the compressor could get seizure to locking inside it and in the worst case the engine might stall at a time when the engine rpm becomes slow, while the vehicle is running.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MK21S	PALETTE	2000 - 2012	278,909
CBA-MK21S	PALETTE	2008~2013	62,213
DBA-MH23S	WAGON R	2000 - 2012	682,605
CBA-MH23S	WAGON K	2008~2012	55,376
DBA-HE22S	ALTO LAPIN	2008~2015	253,381
CBA-HE22S	ALIO LAPIN	2008~2010	3,729
DBA-ML21S	ROOX	2009~2013	164,021
CBA-ML21S	NOOA	2009 2013	9,373

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MJ23S	AZ-WAGON	2008~2012	94,937
CBA-MJ23S	AZ-WAGON	2008~2012	5,721
DBA-MM21S	EL ATD WACON	0010 . 0010	5,738
CBA-MM21S	FLAIR WAGON	2012~2013	122
		TOTAL	1,616,125