

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3774	DATE	Mar 17,2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the inappropriate manufacturing management, the intake duct on direct injection turbo engine may have been manufactured by improper material. Incorrect material would cause the low performance of oil and heat resistant and thereby developing the crack on the duct. The crack on the duct affects the engine capability which would possibly trigger the engine stall, if in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-SJG	「FORESTER」	2015	903
DBA-VAG	「WRX」	2015	2,262
DBA-VM4	「LEVORG」	2015	11,639
DBA-VMG		2015	2,313
		TOTAL	17,117