

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3781	DATE	March.2.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the passenger side frontal airbag dual-stage inflator of the subject vehicles, while the root cause has not been identified, there is a possibility that inflator could rupture during the deployment of the airbag; therefore, for all affected vehicles, the inflator will be replaced with a new one as a precautionary measure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-UZZ40	[SC430]	2008-2010	895
CBA-AZT250	[AVENSIS WAGON]	2008	636
CBA-AZT251			288
CBA-AZT255			159
CBA-AZT250W			464
CBA-AZT251W			392
CBA-AZT255W			95
			TOTAL

(Note) Based on a result of the recovered parts investigation, this recall is to expand the range of the precautionary recall (#3591) filed on June 25, 2015.