## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3782	DATE	Mar.2,2016	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to improper repairing for rejected frame part, hardness of the side stand bracket mounting area goes down. It may cause breakage at the side stand bracket mounting area when parking with side stand, and motorcycle may fall down.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-GX72B	Hayabusa	2016	17
		TOTAL	17