

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3784	DATE	March , 25 , 2016
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The structure of turning clutch is not adequate for durability. The circlip may be broken after certain hours operation. That leads to deteriorate of the turning performance.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-C514	「ER572」	2007～2009	568
KDN-C515	「ER572」	2009～2010	214
	「ER572N」	2010～2012	412
SB-C513	「ER587」	2007～2010	425
KDP-C517	「ER587N」	2010～2013	211
SB-C609	「ER698」	2007～2010	535
KDP-C610	「ER698N」	2010～2013	362
EDR-C608	「ER108」	2007～2010	552
	「ER108N」	2010～2013	371
		TOTAL	3,650