

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3785	DATE	March, 25, 2016
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>① The connection and the end of exhaust pipe may be blocked with mud in wet paddy field. That may set accumulated straw debris on fire due to heat up of the exhaust pipe.</p> <p>② Due to lack of the protection for the straw in the chamber of crop thresher, the accumulated straw on the pulley of thresher may lead to set fire.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-C519	「ER575」	2013～2016	150
WDP-C518	「ER590」	2013～2016	257
WDP-C613	「ER6100」	2013～2016	291
WDR-C612	「ER6120」	2013～2016	536