

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3786	DATE	Mar. 22 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some engines for heavy- and medium-duty buses, tightening of the terminal of battery harness on the starter is improper. If the vehicle continues to be used in this condition, the terminal will become loose and may short-circuit to the motor harness because of vehicle vibration. In the worst case, it may cause fire or the vehicle may become unable to start due to broken starter relay harness.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-MM96FH	「FUSO AERO ACE」	2014	1
QDG-MM97FH		2014～2016	22
QKG-MP35FK	「FUSO AERO STAR」	2015～2015	4
QKG-MP35FM		2013～2016	110
QKG-MP35FP		2013～2016	105
QKG-MP37FK		2013～2014	25
QKG-MP37FM		2015～2015	2
QKG-MP38FK		2014～2016	363
QKG-MP38FM		2014～2016	138
TDG-MM96FH	「FUSO AERO ACE」	2013～2014	10
TDG-MM97FH		2014～2016	77
TKG-MK27FH	「FUSO AERO MIDI」	2013～2016	125
		TOTAL	982