

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3788	DATE	Mar. 31, 2016
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>The control program for engine starter operation is improper on the vehicles equipped with a push start button. If the gearshift lever is operated from P to N soon after the push start button is pushed, the inside of the starter may be burnt. As a result, noise may happen due to the stuck starter inside. If the vehicle is continuously used in such a condition, the engine may not start in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2014-2015	67,581
DBA-LA160S			14,419
DBA-LA150F	STELLA		7,201
DBA-LA160F			3,048
		TOTAL	92,249