

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3791	DATE	March 31, 2016
MANUFACTURER	Unicarriers		
DESCRIPTION OF DEFECT	<p>In the power transmittance device, companion flange for the torque converter transmission has an insufficient durability against the stress level expected to be generated during usage, due to its lack of strength.</p> <p>As such, cracks may form in the companion flange if it's used continuously in the same condition and in worst case, there's a possibility flange may fracture which makes it incapable to transmit power causing travelling impossible.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDM-F177	UNICARRIERS	2 0 1 5	92
YDN-F178	FORKLIFT	2 0 1 6	
YDM-F180			
YDN-F181			
EBT-F176			
YDM-F184			
YDN-F185			
YDM-F187			
YDN-F188			
		TOTAL	92