

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3792	DATE	March 31 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		As regards buses equipped with safety belts to secure wheelchairs inside the vehicles, the inappropriate shape of the side panel of a foot rest can cause the electric wiring for the stop button nipped by the side panel, so that the electric wiring, when it continues to be used as it is, could be damaged, and the function of the stop button could be damaged.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QDG-LV290N1	[ERGA]	2015-2016	14
		TOTAL	14