

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2326	DATE	20. 04. 2016
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained, that in a few cases oil may leak between the clutch slave cylinder and the braided stainless steel brake line. The cause is a burr in the clutch slave cylinder which may damage the gasket of the braided stainless steel brake line. A vehicle that has clocked up a high odometer reading can evince gradu-al impairment of the clutch function.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-R12NA	「BMW R1200GS」	2016	121
EBL-R12NA	「BMW R1200GS-A」	2016	71
EBL-R12NA	「BMW R1200RT」	2016	68
EBL-R12NB	「BMW R1200R」	2016	123
EBL-R12NB	「BMW R1200RS」	2016	221
		TOTAL	604