

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2325	DATE	Apr. 15, 2016
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	Customer Satisfaction - Owner Notified Program: Certain 2010 - 2013 Model Lincoln MKX vehicles.- Replace the brake booster In some of the affected vehicles, it is possible for the brake booster to develop a small tear in the diaphragm under certain driving and environmental conditions. If this occurs, the driver may hear a hissing noise while depressing the pedal and may also experience a "spongy" pedal feel without a noticeable effect on braking performance. If the vehicle is not serviced, the tear will eventually expand and the pedal effort required to stop the vehicle will gradually increase. However, in all cases, the fundamental vehicle braking system remains functional.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Lincoln MKX	2010-2013	171 units
TOTAL			171 units