

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3801	DATE	Apr.13.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the engine fuel delivery pipe, due to improper assembly instructions for tightening the fuel pressure sensor, there is a possibility that the axial force connected to the delivery pipe could be insufficient and may decrease, causing the sealing performance of the tightening portion to degrade. If this occurs, fuel odor may generate and fuel could leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-GRS180 CBA-GRS180 DBA-GRS180	[CROWN]	2003-2007	76,524
DBA-GRS181		2004-2007	6,433
UA-GRS182 CBA-GRS182 DBA-GRS182		2003-2007	95,201
UA-GRS183 CBA-GRS183 DBA-GRS183		2003-2007	10,979
DBA-GRX120	[MARK X]	2004-2007	100,098
DBA-GRX121		2004-2007	8,785
DBA-GRX125		2004-2007	12,290

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GSE20	[IS250]	2005-2007	13,988
DBA-GSE25		2005-2007	1,457
		TOTAL	325,755