

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3795	DATE	April 7, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On DC-DC convertor, due to inappropriate indication for part inspection, a huge voltage may cause damage to the inner circuit board. Therefore, the inside of the convertor may be short-circuited and it causes an inappropriate charging, then a warning lamp may illuminate, in the worst case, resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-DJ5AS	Mazda「DEMIO」	2013	56
LDA-DJ5FS		2013-2014	960
LDA-DK5AW	Mazda「CX-3」	2014	18
LDA-DK5FW		2012-2014	33
DBA-ND5RC	Mazda「ROADSTER」	2014-2015	6
		Total	1073