

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3794	DATE	April 7, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Due to inappropriate fixing process of the damper and the knuckle on the front suspension, tightening torque may be insufficient. Therefore, the nuts may be loose in use process, in the worst case, the nuts and bolts may fall down and the vehicles may be unable to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-DE3AS	Mazda 「ATENZA」	2013	5
DBA-DE 3 FS		2013-2014	81
DBA-DE5FS		2014	1
DBA-DEJFS		2012-2014	76
LDA-DK5AW	Mazda 「CX-3」	2014-2015	114
LDA-DK5FW		2014-2015	331
DBA-LY3P	Mazda 「MPV」	2013	4
		Total	612