## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3787	DATE	Apr 7, 2016	
MANUFACTURER	SUZUKI MO	TOR CORPOR	ATION	
DESCRIPTION OF DEFECT	Due to improper layout of brake hose at front brake line, on turning steering wheel fully, radius of bent hose becomes small, and repetition of the motion might cause crack inside of the brake hose.  Therefore, if using vehicle in such condition, the crack could develop further, brake fluid leaks and brake warning light turns on and in the worst case braking force could decrease.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MK21S	PALETTE	2008~2011	176,089
CBA-MK21S	PALETTE	2008/~2011	58,551
DBA-ML21S	ROOX	2009~2011	74,060
CBA-ML21S	ROOX	2009/~2011	6,604
		TOTAL	315,304