

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3798	DATE	April.4. 2016
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>For some electric power steering (EPS) control units, the EPS assist stop voltage setting was incorrect. In this case, the battery voltage may drop below the EPS assist stop voltage on the occasion of a wide-angle steering, if the battery is deteriorated and cannot be fully charged. Should this happen, the EPS warning light would come on and the power steering assist function could be lost, thereby increasing the steering effort suddenly.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK3	「FIT」	2013~2015	118,715
		TOTAL	118,715