VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicle

CAMPAIGN No.	GAI-2335	DATE	May 31,2016		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	Due to inadequate installation of the air hoses installed in power transmission and braking devices, there are cases of air leaking from hoses when the hoses become unattached at the joint. With such air leaks, the air tank pressure drops and the warning light is lit. Continued use in this condition may lead to, in the worst case, a reduced braking force of brake function and the power transmission being forced into to the neutral position causing a travel failure.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FAUN	ATF90G-4	2014-2015	31
FAUN	ATF220G-5	2015	6
FAUN	ATF400G-6	2015	5
FAUN	RTF600-7	2015	4
FAUN	ATF160G-5	2015	3
		TOTAL	49