

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3810	DATE	May 16, 2016
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	<p>In reference to the fitting strength between the muffler and the tail pipe, due to the design of its welding connections are not appropriate, the cracks of the welding can be caused by vibrations from the engine. Therefore, the tail pipe can be dropped if the machine has been kept in operation under the above condition.</p> <p>The traveling failure can be caused by the melt fracture of the air cleaner case or the leakage of hydraulic oil from the hose (for both traveling / actuation), which results by the exhaust heat directly from the muffler after the dropping of the tail pipe.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A5SDK7	TOYOTA JOBSUN	2015	10
YDN-A5SDK8		2015	15
YDN-A5SDK10		2015	2
TOTAL			27