

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 8 1 1	DATE	M a y . 1 2 . 2 0 1 6
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As the fixing method of the protective sheet for the electrical wires of the main harness is inappropriate, the electrical wires may sometimes be exposed from the protective sheet during the operation of the handle. Therefore, if it is used continuously, the exposed electric wires may contact the peripheral components, and in the worst case scenario, the electric wires may disconnected and that may cause the lighting devices (front light, turn signals and tail light, etc.) or the alarming horn to be deactivated, and furthermore, the engine may stop and not be able to be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RN46J	XSR900	2016	251
		TOTAL	251