

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3812	DATE	May 19 , 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to improper manufacturing of the rear wheel brake, inner diameter of the cylinder that wraps the piston for the parking brake can be wider. Therefore as sealability inside the caliper is low without enough closeness, brake fluid may leak and the warning light may light. In the worst case brake force might decrease.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-ZC32S	SWIFT	2014~2015	5,012
DBA-ZC72S			8,123
DBA-ZD72S			6,283
		TOTAL	19,418