

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3814	DATE	May. 12 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks with 12-speed mechanical-automatic transmission, cracks may occur in the output shaft of the transmission due to insufficient strength of the shaft. If the truck continued to be used in this condition, the cracks will widen and, in the worst case, the output shaft will break. This will result in falling off of the propeller shaft, or letting the propeller shaft move roughly to damage the surrounding parts, causing secondary troubles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FS54JZ	「FUSO SUPER GREAT」	2008~2010	318
BKG-FS55JZ		2008~2010	154
LKG-FS54VZ		2010~2012	104
LKG-FS55VZ		2010~2012	99
QKG-FS54VZ		2010~2014	112
QKG-FS55VZ		2012~2014	113
		TOTAL	900