

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3818	DATE	May 27, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper software of the Airbag control module, in case of turning ignition switch on certain duration after turning ignition switch off, the software could be eliminated.</p> <p>Therefore, the airbag warning lamp would be illuminated and airbags might not be deployed even when a collision occurs.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MA26S	SOLIO	2015~2016	2,912
DAA-MA36S			32,741
DAA-MA46S		2015	30
DAA-FF21S	IGNIS	2016	8,564
DBA-WB32S	BALENO	2016	1,338
CBA-WB42S			276
DAA-MB36S	DELICA D:2	2015~2016	5,596
		TOTAL	51,457