

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2342	DATE	Jun 10, 2016
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2006 Chevrolet Trailblazer vehicles and certain 2006 Chevrolet Trailblazer Ext vehicles. The headlamp driver module (HDM) may not operate properly in the thermal environment of the underhood electrical center. If the HDM is not operating correctly, the low-beam headlamps could fail to illuminate. This failure could be intermittent or permanent. This condition does not affect the high-beam headlamps, marker lamps, turn signals, or fog lamps. Loss of low-beam headlamps, when they are required, could reduce the driver's visibility, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「GH-T360」	「Trailblazer」	2006	51
「GH-T370L」		2006	115
「GH-T370V」		2006	80
		TOTAL	246