VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	3 8 1 7	DAT	TE	Jun.	2. 2016
MANUFACTURER	Nichijo Manufacturing Co.,Ltd.				
DESCRIPTION OF DEFECT	In the engine of the rotary snow plow, For the manufacture of a bolt that secures the connecting rod and the connecting rod cap is inappropriate, there is a thing which the bolt is broken due to fatigue. Therefore, continuing to use as it is, there is a possibility that deviated connecting rod reaches the disabled traveling defeat the engine block.				
ТҮРЕ	COMMERCIAL NAME		MODEL YEAR RECALLED		NUMBER OF VEHICLE
UDS-R03D	「HTR306」		13~201 0053 ~ RO3D-0		1 4 8
			TOTAL	<u>.</u>	148

[Notes] The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.