

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 8 2 2	DATE	June.9.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the electronic control steering (Direct adaptive steering), due to inappropriate program for the detection of the steering turning angle at the engine start, when the engine is started after parking with steering turning, the tire turning angle may be miscalculated and it could cause a difference between the steering turning angle and the tire turning angle. As the result, the tire cannot return straight even if the steering wheel is centered and the vehicle can't start in the direction intended by the driver, if the vehicle continues to be driven in this condition, it may not turn as the driver intends.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HV37	SKYLINE	2014~2015	8,890
DAA-HNV37			2,663
DBA-YV37			120
		TOTAL	11,673