

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3825	DATE	JUN 30,2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for dual-staged passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BL5 CBA-BL5 TA-BL5 UA-BL5	「LEGACY」	2003~2009	65,834
DBA-BL9		2007~2009	1,448
CBA-BLE DBA-BLE UA-BLE		2003~2009	8,749
ABA-BP5 CBA-BP5 TA-BP5 UA-BP5		2003~2009	150,344
CBA-BP9 DBA-BP9 UA-BP9		2003~2009	41,338
CBA-BPE DBA-BPE UA-BPE		2003~2009	22,466
CBA-BPH		2008~2009	1,506
			TOTAL