

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3826	DATE	June.9. 2016
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
UA-RB1	「ODYSSEY」	2003～2004	18,242	
UA-RB2		2003	3,098	
LA-RB1		2003～2004	5,962	
LA-RB2		2003	978	
ABA-RB1		2004～2008		87,234
ABA-RB2				14,359
DBA-RB1				127,296
DBA-RB2				20,637
DBA-GE6		「FIT」	2009	131,900
DBA-GE7	7174			
DBA-GE8	11,520			
DBA-GE9	931			
DBA-RR1	「ELYSION」 「ELYSION PRESTAGE」	2004～2008	63,078	
DBA-RR2			10,089	
DBA-RR3	「ELYSION」		18,863	
DBA-RR4			5,030	
DBA-RR5	「ELYSION PRESTAGE」	2006～2008	5,199	
DBA-RR6			817	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZE2	「INSIGHT」	2009	102,622
DBA-GB3	「FREED」		72,748
DBA-GB4			4,304
ABA-FD2	「CIVIC」	2007～2008	9,653
DBA-FD1		2005～2008	17,486
DBA-FD2		2006～2008	1,769
DAA-FD3	「CIVIC HYBRID」	2005～2008	19,276
DBA-KB1	「LEGEND」	2004～2008	10,005
DBA-KB2		2008	539
DBA-CP3	「INSPIRE」	2007～2008	6,209
DBA-RE3	「CR-V」	2009	1,836
DBA-RE4			1,864
DBA-CU2	「ACCORD」	2008	1,397
DBA-CW2	「ACCORD TOUR」		1,299
ZBA-ZC3	「FCX CLARITY」		8
		TOTAL	783,422