

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 8 2 8	DATE	Jun.17 2016
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	There is a possibility to have a rubber hose broken which is connected to the cooling system for the retarder because of insufficient strength, therefore, when you keep driving the vehicle, it might have leakage of coolant of the engine then might be unable to drive the vehicle at worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
UDS-KRC012	KR-75H	2013~2016	372	
		TOTAL	372	