VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic mport Vehicles

CAMPAIGN No.	3831	DATE	24-June-2016		
MANUFACTURE	KCM Corporation				
DESCRIPTION OF DEFECT	A low pressure hose is assembled on a high pressure section as unsuitable oil hose selection of the rotary snow removal instrument for shovel; loader. In the worst case of snow removing job, the rotary snow removal instrument will not be worked due to burst of hose and oil leakase. And there is apossibility the machine does not control or travel inability due to the oil leakase from oil circuit.				
	COMMERCIAL	MODEL YEAR			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
EDM-HS67	۲ZW40 J	2012	1	Snow remova
EDM-H67	「ZW40DTK」	2014-2015	7	
		TOTAL	8	