

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3832	DATE	June 30,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the inflator for passenger side airbag, the propellant may be deteriorated by the repetitive changes of temperature and humidity due to improper performance in moisture absorption prevention of the propellant. As a result, the inflator body may rupture at the time of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-H82W	「eK-WAGON」 「eK-SPORT」	2006～2013	14,950
DBA-H82W		2006～2013	249,395
CBA-H82A	「TOPPO」	2008～2013	5,394
DBA-H82A		2008～2013	45,150
ABA-H53A	「PAJERO MINI」	2008～2012	4,957
ABA-H58A		2008～2012	33,781
CBA-H92W	「OTTI」	2006～2013	10,197
DBA-H92W		2006～2013	120,960
ABA-H59A	「KIX」	2008～2012	11,300
		TOTAL	496,084