

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3833	DATE	June 30,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the inflator for driver side airbag, the propellant may be deteriorated by the repetitive changes of temperature and humidity due to improper performance in moisture absorption prevention of the propellant. As a result, the inflator body may rupture at the time of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2014~2016	13,723
DBA-CV2W		2014~2016	1,686
DBA-CV5W		2014~2016	2,051
DBA-V83W	「PAJERO」	2014~2016	187
LDA-V88W		2014~2016	308
DBA-V93W		2014~2016	352
LDA-V98W		2014~2016	2,126
		TOTAL	20,433