

**VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	3834	<b>DATE</b>	June 23 , 2016
<b>MANUFACTURER</b>	SUZUKI MOTOR CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	Due to improper welding between a fixing plate for left side seatbelt retractor and a quarter inner panel at rear seat belt, welding strength is not sufficient. Therefore the fixing part of a seat belt retractor on body might be deformed at the time of the collision, it could be unable to restrain a passenger.		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
DAA-FF21S	IGNIS	2016	160
		<b>TOTAL</b>	<b>160</b>