

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3835	DATE	Jun.29.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the stored gas type inflator for the curtain shield airbag assembly of the subject vehicles, due to improper manufacturing, there is a possibility that the inflator tube could not clean completely and the lubricant may remain inside the tube causing the tubes to be welded inappropriately. In this condition, a minute crack could develop in the welded portion and eventually the weld could separate by an increase of the stored gas pressure along with an increase of the temperature in the interior of the parked vehicle. In the worst case, part of the inflator could be ejected into the interior of the vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZVW30	[PRIUS]	2009-2012	710,124
DLA-ZVW35	[PRIUS] [PRIUS PHV]	2009-2012	6,663
DAA-ZWA10	[CT200h]	2010-2012	26,293
		TOTAL	743,080