

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3839	DATE	June 30, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to high absolute humidity, high temperature and high temperature cycling. Therefore, during the airbag deployment, the container of inflator may be broken, components may be scattered, causing passengers to be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-DE3AS	Mazda 「DEMIO」	2007- 2014	16,046
DBA-DE3FS		2007-2014	231,850
DBA-DE5FS		2007-2014	26,691
DBA-DEJFS		2011-2014	71,439
ABF-SKP2V	Mazda 「BONGO」	2010-2016	21,380
ABF-SKP2M		2010-2016	6,454
ABF-SKP2T		2010-2016	17,466
ABF-SKP2L		2010-2015	5,093
DBF-SLP2V		2016	1,551
DBF-SLP2M		2016	620
DBF-SLP2T		2016	1,386
DBF-SLP2L		2016	420

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2VN	NISSAN 「VANETTE」	2010-2015	165
ABF-SKP2MN		2010-2016	9,080
ABF-SKP2TN		2010-2016	17,757
ABF-SKP2LN		2010-2016	3,705
ABF-SKP2VM	MITSUBISHI 「DELICA」	2010-2011	570
ABF-SKP2LM		2010-2011	68
ABF-SKP2MN		2010-2011	424
ABF-SKP2TN		2010-2011	158
		Total	432,323