

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2357	DATE	July13, 2016
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	The Ignition Switch, P/N 71400113, on certain M.Y. 2014.5 – 2016 FXDL model motorcycles built from 1/6/14 through 4/7/16 in Kansas City may become damaged internally due to engineinduced vibration. Vibration from the engine, which the switch is mounted to, may damage the internal electronics of the ignition switch. If this condition remains undetected it could cause the engine to unexpectedly shut off while the motorcycle is being ridden, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-FD4B	LOW RIDER	2015-2016	1172
		TOTAL	1172