

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2359	DATE	July 27, 2016
MANUFACTURER	FCA US LLC (Japanese Importer : FCA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	The power steering hose clamp may not be installed correctly during the manufacturing process. The low pressure power steering return hose may detach and cause a large volume power steering fluid leak. Leaking power steering fluid, in contact with an ignition source, could result in an engine compartment fire without warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MK4924	Jeep Compass	2015Y	165
		Total	165