

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIN No.	Gai -2362	DATE	July 22, 2018
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	<p>In the parts catalogue for the 918 Spyder, the locations for using the screws for securing the seat belt mount and belt reel were mixed up as a result of a work error.</p> <p>Once removed, the screws used to secure the seat belt mount and belt reel must not be reused.</p> <p>New fastening screws will therefore be ordered in accordance with the parts catalogue.</p> <p>We cannot rule out the possibility that due to the mix up in the allocation in the parts catalogue, the wrong fastening screws may have been used for these locations in the Porsche Centre when carrying out assembly work, such as removing and installing seats.</p> <p>In this case, the restraint function of the seat belt system may be impaired in the event of an accident.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	918Spyder	2015	28
		TOTAL	28