

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3845	DATE	July 1, 2016
MANUFACTURER	HKS CO., LTD.		
DESCRIPTION OF DEFECT	Cracking may occur on the floor panel of the vehicle which was modified to the natural gas and gasoline-fueled vehicle due to the insufficient strength examination of the fuel tank's (a gas container's) installation part. The crack may be enlarged with continued use; in the worst case, the floor panel may be damaged resulting in falling-off of the fuel tank.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBE-NCP51V Kai	「PROBOX」	2012~2015	166
DBE-NCP55V Kai	「SUCCEED」	2013~2015	9
		TOTAL	175