

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3850	DATE	July 1, 2016
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	Because the cam bearing is inappropriate, the engine can cause the lack of oil slick. Engine block is worn by a cam shaft impact and oil pump may be broken by abrasion dust. As a result, in the worst case seizure of the engine causes the vehicle can not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-NR6B	NR302	2013-2014	43
TOTAL			43