

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3851	DATE	July 13 ,2016
MANUFACTURER	ISUZU BODY CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate instructions to the layout of the wiring harness for the cornering lamps, the power supply may not be supplied to the electric circuit for the cornering lamps of Road Line Marking Trucks which are customized for drivers to steer both in the driver's seat and passenger seat. This will result in a malfunction of lighting when the cornering lamps are operated to light up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-NPR85YN'KAI	“ELF”	2015/4/1	1
		TOTAL	1

|