VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3852	DATE	July 8 , 2016		
MANUFACTURER	Komatsu Ltd.				
DESCRIPTION OF DEFECT	In the fuel line of the shovel loader, the mounting direction of the pre-filter to protect fuel feed pump is inappropriate. The water in the pre-filter frozen at lower temperature in winter season so as to be closed the fuel inlet. And the worst case, the fuel supply from the tank is no longer possible and the engine is stopped.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
YDM-WA133	「WA40-8」 「WA50-8」	20	15-2016	62
YDM-WA133A	「WA40-8」 「WA50-8」	2015-2016		227
			TOTAL	289