

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3856	DATE	July 14, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the fuel pipe equipped on the captioned vehicles, the tightened torque of the connector bolt may be insufficient due to inappropriate tightening of the bolt. Therefore, looseness of the connector bolt and fuel leakage may result. In the worst case, a fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-DJ5AS	Mazda「DEMIO」	2015	1
LDA-DJ5FS		2015	2
		Total	3